

PART - I
PERFORMA FOR THE SAFETY OF SCHOOL BUILDING

(To be filled by the Head of school/ Institution)

- 1 (a) Name of the school: Somerset International School
- (b) Level/Standard of School:-
- © Whether School is affiliated to C.B.S.E or P.S.E.B. if affiliated then affiliation No. C.B.S.E (New Delhi)
1631170
- 2 Location Village Hadan, P.O: Lambra, Jalandhar
- 3 Plot Area: 2.26 Acre
- 4 Plinth Area 48,480 square feet
- 5 Number of Storey 4
- 6 Year of construction of building. 2015
- 7 If the building has been constructed under the Supervision of the Qualified Engineer, the following details may be given. Yes
- a) Name of the Engineer with Qualification Mr. Vikas Sekhri [B.Tech (Civil)]
- b) Address of the Engineer 360, J.P. Nagar, Jalandhar
- c) Detail of structural drawings used in the construction. Structural drawing attached
- d) Name & Address of Architect with qualification. Mr. Sanjay Kumar (B.Arch) 405 2nd floor
Karan Chamber
Jalandhar
- 8 Whether the building has been constructed for the purpose of
- a) School Yes
- b) Residential purpose and converted for use as a school. No
- 9 Material used for roofs
- a) R.C.C. slabs Yes
- b) R.S. Joists & Battens -
- c) Wooden Joints & Battens. -
- 10 Material used for walls
- a) Mud mortar -
- b) Cement mortar Yes
- c) Plaster i) Lime mortar Yes
ii) Cement mortar Yes
- 11 Flooring :-
- a) Conglomerate Yes
- b) Terrazo -
- c) Brick paving -
- 12 A detailed drawing indicating dimensions of the rooms alongwith size and location of doors and windows. Attached
- 13 Whether fire safety certificate obtained from concerned fire officer. Yes
- 14 It is also certified that there is no any court case or stay is pending regarding this building in any Hon'ble Court. No Court case

Somerset International School
Principal

Aff. No: 1631170
Signature and Stamp of the Head
School Code: 21162

Jhadha 09/07/22

PART - II

SCHOOL BUILDING SAFETY CERTIFICATE

(TO BE FILLED BY THE S.D.E OF P.W.D. B&R DEPARTMENT)

Name of the School: *Somerset International School*
Abadan Campus, Kala Sanghian Road Jalandhar.

- 1) This office Assistant Engineer/Junior Engineer visited the above mentioned School on _____ and have visually inspected it for its safety and find it fit for normal use as a school building.
- 2) In case any addition or expansion and modification to this building is to be carried out same may be done under the supervision of a technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.
- 3) In case the building is effected by flood, or if there is settlement of walls/ foundation or sagging of roofs etc. immediately inspection of the undersigned be arranged to check the stability and the safety of the building.
- 4) This building is found visually safe hence it is expected that it can be safely occupied for normal use up to (indicate year upto which it can be used) 2019-20 *2023-24 upto 31-03-2024*

Ref. No. 54

Dated 27/07/2023

[Signature]
Sub Divisional Engineer
Constn S/D 3, PWD B&R Br.,
Jalandhar, Cantt.

[Signature]
A/E

Challan No. - *727/225*

Date - *27/7/2023*

Amount. - *10,000/-*

21